
Star Wheel Product Improvement



The 030-4641 star wheel assembly has been updated for improved reliability and ease of installation. The assembly transitions from a four-bolt block to a two-bolt block. Some installations will require additional filler plate.

- \rightarrow
- Large Square Baler Models Impacted:
- AGCO/Massey/Challenger 21/2200 Series

Setups with GREY twine diverter will use black 2 hole filler plate with new style star wheels.

New two-bolt block Star Wheels 030-4641 Setups with BLACK twine diverter will NOT use 2 hole black filler plate with new style star wheels.



Note – remove 4 bolt plate from baler





For more information contact Harvest Tec

Email: info@harvesttec.com Phone: 1-800-635-7468